

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 6

Sewershed : Gwynn Falls

Company : URS

Date : 10/10/2008

Test to be Performed :
Smoke : X Dyed Water :

Ground Condition :
Dry : X Damp : Wet :


Supervisor : John Daly

Manhole ID : S05OO1003MH

Test ID : S1032-034033

Notifications (Residents, Fire, 311) :
Yes

Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



LEGEND		Defect Code	Defect Description	Defect Code	Defect Description
		SL	Service Lateral	CB	Catch Basin
	SMOKE OBSERVATION	TJ	Transition Joint	SD	Storm Ditch
	BLOWER LOCATIONS	DD	Driveway Drain	SWMH	Storm Manhole
	WW_ManholeJunction_1	WWD	Window Well Drain	MAIN	Main Sewer
	WWW_Sewer	STRD	Stairwell Drain	SANMH	Sewer Manhole
	SMOKE RUN	AD	Area Drain	CO	Cleanout
		DS	Downspout	OTHER	Other
		DSC	Downspout Connection	IOB	Inside of Building
		FD	Foundation Drain		

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 2 of 6

Sewershed : Gwynn Falls

Company : URS

Date : 10/10/2008

Test to be Performed :
Smoke : X Dyed Water :

Ground Condition :
Dry : X Damp : Wet :

Supervisor : John Daly


Manhole ID : S05001003MH

Test ID : S1032-034033

Notifications (Residents, Fire, 311) :
Yes

Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Service Lateral; Smoke: Heavy; Status: Private Property

Landscape



Defect



ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Private Property

Landscape



Defect



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 3 of 6

Sewershed : Gwynn Falls

Company : URS

Date : 10/10/2008

Test to be Performed :
Smoke : X Dyed Water :

Ground Condition :
Dry : X Damp : Wet :

Supervisor : John Daly


Manhole ID : S05001003MH

Test ID : S1032-034033

Notifications (Residents, Fire, 311) :
Yes

Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Main Sewer; Smoke: Heavy; Status: Private Property


Landscape



Defect



ID



Location: N/A; Type: Stairwell Drain; Smoke: Heavy; Status: Private Property

Landscape




Defect



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 4 of 6
Sewershed : <u>Gwynn Falls</u>	Company : <u>URS</u>	Date : <u>10/10/2008</u>
Test to be Performed : Smoke : <u>X</u> Dyed Water : <u> </u>	Ground Condition : Dry : <u>X</u> Damp : <u> </u> Wet : <u> </u>	Supervisor : <u>John Daly</u>
Manhole ID : <u>S05001003MH</u>	Test ID : <u>S1032-034033</u>	Notifications (Residents, Fire, 311) : <u>Yes</u>
Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)		

ID



Location: N/A; Type: Foundation Drain;
Smoke: Heavy; Status: Private Property

Defect



Landscape



Defect



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 5 of 6

Sewershed : Gwynn Falls

Company : URS

Date : 10/10/2008

Test to be Performed :
Smoke : X Dyed Water :

Ground Condition :
Dry : X Damp : Wet :

Supervisor : John Daly


Manhole ID : S05001003MH

Test ID : S1032-034033

Notifications (Residents, Fire, 311) :
Yes

Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Service Lateral; Smoke: Heavy; Status: Private Property


Landscape



Defect



ID






Location: N/A; Type: Service Lateral; Smoke: Heavy; Status: Private Property

Landscape



Defect



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 6 of 6
Sewershed : <u>Gwynn Falls</u>	Company : <u>URS</u>	Date : <u>10/10/2008</u>
Test to be Performed : Smoke : <u>X</u> Dyed Water : <u> </u>	Ground Condition : Dry : <u>X</u> Damp : <u> </u> Wet : <u> </u>	Supervisor : <u>John Daly</u>
Manhole ID : <u>S05OO1003MH</u>	Test ID : S1032-034033	Notifications (Residents, Fire, 311) : <u>Yes</u>
Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)		
<div> <div> ID <div>  <p>Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Private Property</p> <p>Landscape</p>  <p>Defect</p>  </div> </div> </div>		